

# BELZONA PROTECTS 98% SULFURIC ACID CONTAINMENT AREA


ID: 1207

Industry: Power  
Application: TCC-Tanks and Chemical Containment Areas  
Substrate: Concrete  
Products: Belzona® 4311 (Magma CR1)

Customer Location: Power Plant, Alabama USA  
Application Date: December 2007

## Problem

Sulfuric Acid containment area coating had failed and needed re-coating.



## Photograph Descriptions

\* Old coating being removed , \* Belzona® 4311 being applied , \* & 4. Completed application ,

## Application Situation

98% Sulfuric Acid containment area in water treatment plant.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-15. Old coating was removed using high pressure water blasting. Belzona® 4311 was applied to both containment and tank stands.

## Belzona Facts

Belzona has been used for years in many of Alabama Powers plants. Customer trusted product and longevity of previous applications.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve