

BELZONA REFURBISHES RUBBER-LINED PUMP

ID: 123

Industry: Sugar

Application: SHM-Solids Handling Machinery

Customer Location: Sugar Cane Mill in Texas, U.S.A.

Application Date: 1985

Substrate: Cast Iron

Products: * Belzona® 2111 (D&A Hi-Build Elastomer),

Problem

Pump casing and impeller suffer from erosion/corrosion due to the abrasive nature of the ash slurry.



Photograph Descriptions

- * View of uncoated casing. ,
- * Application of coating material to impeller. ,
- * Casing completely coated with Belzona® 2000 Series product. ,

Application Situation

Ash slurry pump

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet SHM-9.

Belzona Facts

The Belzona® 2000 Series Elastomeric Polymers afforded the casing with the necessary protection against abrasion and impact.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve