

# BELZONA "DELIVERS" A SANITARY FLOORING SOLUTION


ID: 1232

Industry: *Buildings & Structures*  
Application: *FPA-Floor Problem Areas*  
Substrate: *Plywood*  
Products: *\* Belzona® 5811 (Immersion Grade) ,*

Customer Location: *Church charity organization, Texas*  
Application Date: *2006*

## Problem

*The raw plywood floor with no sealant would be difficult to maintain and keep clean in an area that required a very sanitary environment.*



## Photograph Descriptions

- \* The portable birthing center ,
- \* Floor prior to coating with walls taped off ,
- \* Finished Belzona® 5811 flooring application ,

## Application Situation

Charitable members of a Texas church were fabricating a portable birthing trailer that would eventually be shipped to Guatemala in an effort to offer a sanitary medical facility for use in an impoverished area that suffered from a high birthing mortality rate.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-3. The walls were taped off approximately 2 inches up the vertical edge, sanded, cleaned then coated with two coats of Belzona® 5811 with minimal Surefoot aggregate added during the first coat process.

## Belzona Facts

This product was donated through the Belzona Houston Distributorship and one of its Consultants at no cost to the church mission organization. An alternative to 5811 was to purchase an inferior floor coating from a hardware store which would not have had the same trouble-free application or long-lasting result.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve