

BELZONA EMERGENCY SHAFT REPAIR AT PULP & PAPER FACILITY

ID: 1235

Industry: *Pulp & Paper*

Customer Location: *Pulp and Paper plant, Memphis, Tennessee, USA*

Application: *MPT-Mechanical Power Transmission*


Application Date: *2008*

Substrate: *Stainless steel*

Products: *Belzona® 1221 (Super E Metal)*

Problem

A bearing had run dry of lubrication and caused the entire line to shut-down.



Photograph Descriptions

* Shaft prior to repair , * Shaft during repair with former in place , * Shaft after repair ,

Application Situation

Shaft on the Primary paper machine.

Application Method

Application was carried out in accordance with Belzona Know-How System leaflet MPT-2.

Belzona Facts

This roller was a critical in the operation of the plant. With this machine down the entire facility went down. The repair was performed during the lunch hour, saving thousands of dollars in down-time.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve