

# BELZONA EMERGENCY SHAFT REPAIR AT PULP & PAPER FACILITY

ID: 1235

Industry: *Pulp & Paper*

Customer Location: *Pulp and Paper plant, Memphis, Tennessee, USA*

Application: *MPT-Mechanical Power Transmission*

Application Date: *2008*

Substrate: *Stainless steel*

Products: *Belzona® 1221 (Super E Metal)*

## Problem

*A bearing had run dry of lubrication and caused the entire line to shut-down.*



## Photograph Descriptions

\* Shaft prior to repair , \* Shaft during repair with former in place , \* Shaft after repair ,

## Application Situation

Shaft on the Primary paper machine.

## Application Method

Application was carried out in accordance with Belzona Know-How System leaflet MPT-2.

## Belzona Facts

This roller was a critical in the operation of the plant. With this machine down the entire facility went down. The repair was performed during the lunch hour, saving thousands of dollars in down-time.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve