

TANK BASE SEALING WITH BELZONA PRODUCT

ID: 1240

Industry: Power

Customer Location: Power Station, Portland, Philadelphia
USA

Application: GSS-Gaskets, Seals and Shims

Application Date: August 2003

Substrate: Steel and concrete

Products: * Belzona® 3111 (Flexible Membrane),

Problem

Corrosion at chine angle and water getting under the tank bottom



Photograph Descriptions

- * View of the tank ,
- * Chime angle before application ,
- * & 4. Finished application ,

Application Situation

Oil storage tank.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet GSS-3.

Belzona Facts

This is a well proven system for reducing corrosion around tank base where moisture is penetrating beneath tank base.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve