

# BELZONA ROOF SYSTEM PROVIDES ADDED BENEFITS

ID: 1254

**Industry:** *General Industry* **Customer Location:** *Chocolate manufacturer, Kansas City*  
**Application:** *RPA-Roof Problem Areas* **Application Date:** *March 2008*  
**Substrate:** *Rolled roofing, mastic, brick and clay tile*  
**Products:** *Belzona® 3111 (Flexible Membrane) Belzona® 4111 (Magma Quartz)*

## Problem

*Minor leaks were causing unsanitary conditions in the kitchen and the HVAC system could not keep up with major temperature and humidity fluctuations causing discoloration in the highly decorative chocolates.*



## Photograph Descriptions

\* Storefront of world renowned chocolate maker , \* View of the roof prior to remediation , \* Application in progress , \* Completed application ,

## Application Situation

Roof over a kitchen and retail shop.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets RPA-1, -8, -10 and -11.

## Belzona Facts

The owner remarked about the noticeable difference in temperature and humidity control after just the first coat of Belzona® 3111 was applied. Since the completion of the project, this operation has not had to pursue an HVAC upgrade and the chocolates are once again flawlessly beautiful and delicious.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve