

CHURCH HAS LONG HISTORY WITH BELZONA

ID: 1268

Industry: Buildings & Structures Customer Location: Church, Richmond, Virginia USA

Application: RPA-Roof Problem Areas Application Date: Mid 1980s and 2004

Substrate: Tar

Products: * Belzona® 3111 (Flexible Membrane),

Problem

The dome roof has a lot of movement and was very hard to keep from leaking.









Photograph Descriptions

- * 1. & 2. Applying Belzona Flexible Membrane,
- * 3. Spraying the top of the dome,
- * 4. The roof in 2006,

Application Situation

Domed roof on Church.

Application Method

Application was carried out in accordance with Belzona Know-How System leaflet RPA-1. Spray application was used to aid application.

Belzona Facts

Belzona has provided an attractive and economical solution that effectively sealed the roof for the church. The original tar roof proved unsatisfactory. Belzona® 3111 was applied in the mid 1980s and proved to be a successful solution for approximately 20 years. The Church was so happy with the Belzona solution that they decided to restore the roof with a new application of Belzona® 3111 in 2004. The church continues to look to Belzona for solutions for its structural problems.

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are
FS 695214 manufactured under an ISO
ISO 14001:2015 9000 Registered Quality
EMS 695213 Management System.

BELZONA®
Repair • Protect • Improve