

# BELZONA SEALS HYDRAULIC LEAK

ID: 1297

Industry: *General Industry*

Customer Location: *Manufacturer of Stone and Marble Products*

Application: *VPF-Valves, Pipes and Fittings*

Application Date: *August, 2009*

Substrate: *Steel*

Products: *\* Belzona® 1111 (Super Metal) ,*

## Problem

*Hydraulic pipe had started to leak causing the fluid to drip onto the electrical circuit panel, causing a shutdown.*



## Photograph Descriptions

- \* Leaking weld joint ,
- \* Surface preparation ,
- \* Completed repair ,

## Application Situation

Hydraulic system of press for stone products

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a. A wrap using the Belzona® 1111 with Belzona® 9341 (Reinforcement Tape) was used to encapsulate the leaking weld.

## Belzona Facts

Repair was able to stop the leak and get the operating press back up and running in a short amount of time minimizing disruption to production.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

[www.belzona.com](http://www.belzona.com)

