

BELZONA PROTECTS KORT NOZZLES

ID: 1332

Industry: *Marine*
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Tug boat operator, Egypt*
Application Date: *May 2009*

Substrate: *Mild Steel*
Products: ** Belzona® 1321 (Ceramic S-Metal) ,*

Problem

The Kort nozzles were suffering badly from erosion corrosion.



Photograph Descriptions

- * The boat in dry dock ,
- * Grit blasting the nozzles ,
- * Applying of Belzona® 1321 ,
- * Completed application ,

Application Situation

Pair of kort nozzles on tug boat

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-2.

Belzona Facts

Belzona successfully solved this problem and provided long term protection to the nozzles from excessive erosion-corrosion.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve