

# BELZONA KEEPS TIRE ROLLING

ID: 1336

Industry: *Mining & Quarrying*  
Application: *SHM-Solids Handling Machinery*

Customer Location: *Mine, Canada*  
Application Date: *July 2005*

Substrate: *Rubber*  
Products: *\* Belzona® 2211 (MP Hi-Build Elastomer) ,*

## Problem

*Damage on tire sidewall was exposing steel reinforcement to corrosion*



## Photograph Descriptions

\* The equipment Crack was veed out and prepared with Belzona roughing brush Belzona® 9341 (reinforcement Tape) incorporated for additional strength The completed repair ,

## Application Situation

Damaged tire needed fast insitu repair.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-9.

## Belzona Facts

Belzona repair carried out quickly with tire in place. high adhesion and elasticity of Belzona Elastomer copes with extremes of service and protects tire from further deterioration.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve