

BELZONA KEEPS GARAGE SAFE AND CLEAN

ID: 1343

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 5231 (SG Laminate) ,

Customer Location: City Authority, Canada
Application Date: October 2007

Problem

The original floor coating lasted only 12 months and cleaning the surface was a big problem because of the rough surface.



Photograph Descriptions

- * Surface preparation using Blastrac ,
- * Application of Belzona® 5231 gray (3 coats) ,
- * Application of Belzona® 5231 yellow ,
- * Completed application, clean and safe ,

Application Situation

Concrete floor in Public Works garage.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-3. The concrete was abraded to remove the existing coating and profile the concrete. Areas masked off and Belzona® 5231 Yellow and Gray used for demarcation.

Belzona Facts

For our customer it was very important that the Belzona® 5231 would resist chemicals, especially oil. They also required that the surface was anti-slip. After 2 years in service only small touch-ups were done due to large volume of traffic in garage. Customer very satisfied and proud of the new look. They recommended our solution to the fire department.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve