

# Belzona Waterproofs Sunroom Roof

ID: 1352

Industry: *Buildings & Structures*  
Application: *RPA-Roof Problem Areas*  
Substrate: *Asphalt*  
Products: *\* Belzona® 3111 (Flexible Membrane) ,*

Customer Location: *Residential Roof in Ontario*  
Application Date: *June, 2009*

## Problem

*The roof and flashing on this customers sunroom was allowing water to enter and damage walls and belongings.*



## Photograph Descriptions

- \* Applying Belzona® 3911 (Conditioner) ,
- \* Initial application of Belzona® 3111 incorporating Reinforcing sheet in 1st Coat ,
- \* & 4 Finished application ,

## Application Situation

A poor roofing job left customer with a leaking sunroom.

## Application Method

Using modified Belzona Know-How Systems Leaflet RPA-1, a fully reinforced Belzona® 3111 System was applied.

## Belzona Facts

When the roof began leaking, the customer looked to the contractor to honor their warranty, but discovered that the contractor was out of business. Belzona provided the solution the customer was looking for and now dry walls and floors keep this customer a Belzona believer.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

