

BELZONA RESTORES RIVER WATER PUMP

ID: 1362

Industry: Water / Wastewater

Application: CEP-Centrifugal Pumps

Substrate: Cast iron

Products: * Belzona® 1111 (Super Metal) ,
* Belzona® 1321 (Ceramic S Metal) ,

Customer Location: Water treatment works, Iowa

Application Date: August 2009

Problem

Erosion corrosion caused by sand and solids drawn from the river.



Photograph Descriptions

- * Damaged area on pump ,
- * Repairs underway with Belzona® 1111 ,
- * Rebuild completed with Belzona® 1111 ,
- * Completed application after application of Belzona® 1321 ,

Application Situation

River water intake pump for water treatment plant.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets CEP-3 and -5

Belzona Facts

Belzona was chosen due to years of successful pump repairs with this customer. The pump was salvaged using around \$1,000 of Belzona materials, a fraction of the replacement cost.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve