

# Reconstrucción de forro (liner) interno de Slurry Tank

ID: 1384

Industria: Energía

Ubicación del cliente: Planta Generadora Eléctrica, Guatemala C. A.

Solicitud: Maquinaria de Manejo de Sólidos

Fecha de aplicación: Marzo 2007

Sustrato: Acero al Carbón

Productos: \* Belzona® 2111 (D&A Hi-Build Elastomer),

\* ><input id="jsProxy" onclick="jsCall();" type="hidden" /> ,

## Problem

Personal de mantenimiento no se percató que el tanque poseía forro (liner) interno y abrió un manhole en la parte superior.



## Descripciones de fotografías

- \* Tanque de slurrys ,
- \* Aplicando Belzona ,
- \* Revisi&oacute;n con spark tester ,

\* ><input id="jsProxy" onclick="jsCall();" type="hidden" /> ,

## Situación de la aplicación

Tanque agitador de lodos con capacidad de 22,000 galones.

## Método de aplicación

De acuerdo a las Instrucciones de Uso Belzona SHM-9.

## Datos de Belzona

Ingenieros Finlandeses acostumbrados a utilizar otro producto; se les explicó procedimientos y aplicaciones exitosas Belzona y

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Reparar • Proteger • Mejorar

Copyright © Belzona International Limited 2024

autorizaron la aplicación.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

|                |                           |
|----------------|---------------------------|
| ISO 9001:2015  | Belzona products are      |
| FS 695214      | manufactured under an ISO |
| ISO 14001:2015 | 9000 Registered Quality   |
| EMS 695213     | Management System.        |

[www.belzona.com](http://www.belzona.com)

