

BELZONA PROTECTS HEAT EXCHANGER TUBE SHEETS

ID: 1385

Industry: Buildings & Structures

Application: CEP-Centrifugal Pumps

Substrate: Carbon Steel

Products: * Belzona® 1111 (Super Metal) ,
* Belzona® 1321 (Ceramic S-Metal) ,

Customer Location: Chemical Plant, Mexico

Application Date: April, 2006

Problem

Erosion corrosion protection required on tube sheets to prevent further loss of metal that could otherwise lead to leakage, loss of efficiency and contamination.



Photograph Descriptions

- * Corroded tube sheet ,
- * After grit blasting ,
- * 1st coat of Belzona® 1321 ,
- * Completed application with corks removed from tubes ,

Application Situation

Heat exchanger tube sheets in Chemical plant.

Application Method

Application was carried out in accordance with Belzona System Leaflets HEX-1 & -3

Belzona Facts

The equipment was returned to service in just 3 days, representing a gain in the order of \$30,000.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve