

BELZONA REBUILDS BEARING PLATES ON VERTICAL BORER

ID: 139

Industry: *General Industry*

Customer Location: *Steel Manufacturer Engineering Workshop*

Application: *MPT-Mechanical Power Transmission*

Application Date: *March 1997*

Substrate: *Steel*

Products: ** Belzona® 1131 ,*

Problem

White metal bearing plates badly worn/scored due to oil starvation. Manufacturer of this unit has ceased trading so replacement part is unobtainable.



Photograph Descriptions

- * The problem area - excessive wear to white metal plates. ,
- * Application of Belzona® 1131. ,
- * Chuck going back into machine to form Belzona® 1131. ,
- * The finished job with oil grooves cut into Belzona® 1131. ,

Application Situation

Craven 90" dia. Vertical Borer

Application Method

The application was carried out in accordance with Belzona Know-How Leaflet MPT-9.

Belzona Facts

The repaired machine now runs quieter and more smoothly, providing a higher standard of finish to machined components.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve