

Belzona makes grit trucks fit for the winter

ID: 1391

Industry: General Industry

Application: SHM-Solids Handling Machinery

Customer Location: Local Authority Switzerland

Application Date: 2003 and October 2009

Substrate: Steel

Products: * Belzona® 1321 (Ceramic S-Metal) ,

Problem

Auger screws from salt gritting trucks get worn due to the abrasive effect of the salt grit and corrosion resulting in shorter than desired life expectancies.



Photograph Descriptions

- * Auger screw after grit blasting ,
- * Application of the first coat of Belzona® 1321 (blue) ,
- * Finished first coat ,
- * Finished application with second coat of Belzona® 1321 (grey) ,

Application Situation

Screw auger from a road gritting truck

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet SHM-14. Two coats of Belzona® 1321 were applied to the grit blasted steel substrate.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Belzona Facts

The pictures show the coating of a new screw auger. This particular application resulted through the success in 2003 of a smaller version of this auger screw, similarly protected with Belzona® 1321. After 6 years the screw was still in service and in good condition and exceeding the customer's expectation.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

