

BELZONA KEEPS HOSPITAL LAUNDRY BILLS DOWN

ID: 140

Industry: General Industry

Application: VPF-Valves, Pipes and Fittings

Substrate: Rubber

Products: * Belzona® 2211 (MP Hi-Build Elastomer) ,

Customer Location: Hospital

Application Date: Ongoing since 1994

Problem

Wear and tear in service causes splits, in addition to mechanical damage caused by sharp objects left in clothing (a common occurrence).



Photograph Descriptions

- * The laundry press in operation ,
- * Typical split prepared and ready to have Belzona® applied ,
- * Completing the Belzona® 2211 application ,

Application Situation

Press used to squeeze water from laundry prior to drying. They operate at pressures up to 270 bar.

Application Method

Application was carried out in accordance with Belzona System leaflet VPF-5.

Belzona Facts

Typical Belzona repairs cost £10-20 as opposed to a new diaphragm at over £1400. At this hospital some diaphragms have been repaired 5 and 6 times.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve