

# BELZONA KEEPS HOSPITAL LAUNDRY BILLS DOWN

ID: 140

**Industry:** General Industry  
**Application:** VPF-Valves, Pipes and Fittings  
**Substrate:** Rubber  
**Products:** \* Belzona® 2211 (MP Hi-Build Elastomer) ,

**Customer Location:** Hospital  
**Application Date:** Ongoing since 1994

## Problem

*Wear and tear in service causes splits, in addition to mechanical damage caused by sharp objects left in clothing (a common occurrence).*



## Photograph Descriptions

- \* The laundry press in operation ,
- \* Typical split prepared and ready to have Belzona® applied ,
- \* Completing the Belzona® 2211 application ,

## Application Situation

Press used to squeeze water from laundry prior to drying. They operate at pressures up to 270 bar.

## Application Method

Application was carried out in accordance with Belzona System leaflet VPF-5.

## Belzona Facts

Typical Belzona repairs cost £10-20 as opposed to a new diaphragm at over £1400. At this hospital some diaphragms have been repaired 5 and 6 times.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve