

Belzona repairs casing of a cement ball mill

ID: 1417

Industry: *Cement*
Application: *SHM-Solids Handling Machinery*

Customer Location: *Cement plant, Egypt*
Application Date: *November 2008*

Substrate: *Cast iron*
Products: ** Belzona® 1121 (Super XL-metal) ,*

Problem

Wear on the casing needed to be rebuilt before the bolting of the new wear plates.



Photograph Descriptions

- * General view of the mill. ,
- * Wear on the shell after dismantling the plates. ,
- * Application of Belzona® 1121. ,
- * Completed application. ,

Application Situation

Ball mill used to grind limestone in cement production.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet SHM-7.

Belzona Facts

Belzona successfully solved this problem in a moderate price.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve