# **BELZONA KEEPS OS&D HOSE IN SERVICE**

| Industry:    | Marine                                     |
|--------------|--|
| Application: | SOS-Ships and Offshore Structures          |
|              |  |
| Substrate:   | Rubber and exposed fabric reinforcement    |
| Products:    | * Belzona® 2111 (D&A Hi-Build Elastomer) , |

Customer Location: Liquid bulk storage terminal, NJ Application Date: October 2009

## Problem

When inspected by the United States Coast Guard, even superficial scuffs and tears in the outer cover can result in hoses being tagged "out of service". Inspection showed that the reinforcement fabric had not been damaged.



### **Photograph Descriptions**

- \* Hose #9970 with 3 scuffed up areas exposing reinforcement fabric ,
- \* Patch #3 area taped off and abraded ,
- \* Patch #4 area taped off with Conditioner applied ,
- \* Completed and ready for inspection ,

#### **Application Situation**

Scuffs and tears to the cover of 8" OS&D (Oil Suction & Discharge) hoses.

### **Application Method**

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-12.

### **Belzona Facts**

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 FS 695214 ISO 14001:2015 EMS 695213

Belzona products are manufactured under an ISO 9000 Registered Quality Management System.

www.belzona.com



ID: 1426

A typical 8" OS&D hose can cost \$3500 depending on length. Superficial damage, meaning damage to cover only, is common when dragged over docks and railings. The Coast Guard, however, can require these hoses be retired from service. If there is no damage to the reinforcement fabrics, a Belzona® 2111 patch system, when fully documented with before and after pictures, has been accepted by the USCG. These specific patches cost approx \$1200 in material and labor. 5 patches were installed on three hoses saving the customer approx \$11,000 in replacement costs

For more examples of Belzona Know - How In Action, please visit https://khia.belzona.com

ISO 9001:2015 Belzona products are FS 695214 ISO 14001:2015 EMS 695213

manufactured under an ISO 9000 Registered Quality Management System.

www.belzona.com

