

CONVEYOR ROLLERS ON DREDGER RESTORED WITH BELZONA

ID: 1433

Industry: *Marine*
Application: *SOS-Ships and Offshore Structures*

Customer Location: *Fleet Owner, Russia*
Application Date: *September 2009*

Substrate: *Steel*
Products: ** Belzona® 1111 (Super Metal) ,*

Problem

After dismantling, 17 rollers were revealed to be damaged especially bearings, shaft journal and mounting seats.



Photograph Descriptions

- * General view of dismantled rollers ,
- * View of the defects on the rollers ,
- * & 4. A completed application ,

Application Situation

Customer was carrying out planned maintenance to their dredger. The conveyor system was dismantled for inspection.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet SOS-6, which is also approved by Russian Maritime Register of Shipping.

Belzona Facts

The customer decided put into practice to apply composite repairs by our trained distributor. Customer has received quintessence

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve

and innovative polymeric repair for their damaged rollers. With the repair customer received high quality of service, guarantee and satisfactory repair.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

