

BELZONA USED TO RESTORE CORRODED FLANGE ON CHIMNEY


ID: 144

Industry: General Industry
Application: GSS-Gaskets, Seals and Shims
Substrate: Steel
Products: * Belzona® 2221 ,
* Belzona® 4111 ,
* Belzona® 4311 ,

Customer Location: Fertilizer manufacturer in France
Application Date: August 1996

Problem

The flange faces and the removable gasket had been attacked and corroded by the chemicals passing through the unit. In places the depth of corrosion on the flanges was 20-30mm.



Photograph Descriptions

- * The difficult working situation on the chimney ,
- * The flange rebuilt and protected ,
- * Belzona® 2221 used to cast new gasket ,

Application Situation

An acid vapour evacuation unit installed on top of a high chimney

Application Method

Application was carried out using suitably modified techniques covered in Belzona System Leaflets GSS-2, VPF-1, 2 & 13.

Belzona Facts

Ease of use was an important factor given the difficult working situation. The excellent chemical resistance of Belzona® 4311 has prevented further corrosion occurring on the flange.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve