

BELZONA REPAIRED STEPS IN GREAT CONDITION AFTER 5 YEARS

ID: 1458

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4131 (Magma Screed) ,

Customer Location: Local City Council, N.East England
Application Date: May 2005

Problem

Due to the steps being on the sea front, over a number of years they had deteriorated where the nosings were damaged and in dangerous condition.



Photograph Descriptions

- * Steps before repair ,
- * Immediately after repair ,
- * Steps after 5 years use ,
- * Close up showing no deterioration after 5 years. ,

Application Situation

Promenade steps on coast needing repairs.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

Belzona Facts

The customer had previously carried out localised repairs using alternative concrete repair materials. These products, however,

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve

were not effective due to poor adhesion and the nature of the coastal environment. An inspection of the Belzona repairs was carried out after 5 years and there is no signs of deterioration or damage to the step nosings.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

