

# BELZONA REPAIRED STEPS IN GREAT CONDITION AFTER 5 YEARS (2)

ID: 1459

Industry: Buildings & Structures  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona® 4131 (Magma Screed) ,

Customer Location: Local City Council - N.East England  
Application Date: May 2005

## Problem

Due to the promenade steps being on the sea front, over a number of years they had deteriorated where the nosings were damaged and in dangerous condition.



## Photograph Descriptions

- \* Steps before repair in May 2005 ,
- \* Steps immediately after repair in May 2005 ,
- \* Steps five years on in May 2010 ,
- \* Further view of steps after five years service. ,

## Application Situation

Promenade steps on coast needing repairs.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet FPA-1.

## Belzona Facts

The customer had previously carried out localised repairs using alternative concrete repair materials. The products, however, were

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve

not effective due to poor adhesion and the nature of the coastal environment. An inspection of the Belzona application was carried out after 5 years and there is no signs of deterioration or damage to nosings whatsoever.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

