

BELZONA REPAIRS LIVE LEAK ON TRANSFORMER

ID: 1490

Industry: Power
Application: VPF-Valves, Pipes and Fittings
Substrate: Steel
Products: * Belzona® 1161 (Super UW Metal) ,
* Belzona® 1291 (ES-Metal) ,

Customer Location: Electricity Distribution Company, UK
Application Date: 2007

Problem

Oil leak causing environmental contamination.



Photograph Descriptions

- * Leak area ,
- * Leak stopped with Belzona® 1291 ,
- * Application completed with Belzona® 1161 ,

Application Situation

Pipework on oil filled transformer.

Application Method

Application was carried in accordance with Belzona Know-How System leaflet VPF-11a. Belzona® 1291 used to firstly seal the live leak. The pipework was then encapsulated to prevent further leakage.

Belzona Facts

The costly need to drain down the oil to effect a repair (£8,000) was eradicated, the Belzona repair was carried out in less than 2 hours.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve