

BELZONA REPAIRS SEDIMENT COLLECTOR DRAIN PIPE

ID: 1494

Industry: Power
Application: VPF-Valves, Pipes and Fittings
Substrate: Carbon Steel
Products: * Belzona® 1291 (ES Metal) ,
* Belzona® 1161 (Super UW Metal) ,

Customer Location: Power company, Japan
Application Date: December, 2009

Problem

Industrial water was leaking from the corroded drain pipe.



Photograph Descriptions

- * Surface preparation completed ,
- * Leak stemmed with Belzona® 1291 ,
- * Belzona® 1161 and Reinforcement Tape applied to complete repair ,

Application Situation

Sediment removal equipment for Condenser water feed

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet VPF-11a. Belzona® 1291 was used to stem the live leak. Once no leaking was ensured, Belzona® 1161 plus Belzona® 9341 (Reinforcement Tape) was immediately used to overcoat the area to create a permanent repair.

Belzona Facts

Belzona repaired the corroded pipe without disruption to services. This provided the customer with a cost effective solution. Surface tolerance of Belzona® 1161 enables such repairs to be carried out without draining down the equipment.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

**BELZONA**
Repair • Protect • Improve