

BELZONA STOPS LEAK DRAIN PIPE AND HOT WELL PUMP

ID: 1498

Industry: Water / Wastewater

Application: HEX-Heat Exchangers

Substrate: Metal Steel

Products: * Belzona 1161 (Super UW Metal) ,

* Belzona 1291 (ES-Metal) ,

* Belzona 9341 (Reinforcing Tape) ,

Customer Location: Illinois, USA

Application Date: December 2008

Problem

Leaking drain pipe and hot well pump at Water Treatment Plant



Photograph Descriptions

- * 1. Overview of the large sized hole on drain pipe ,
- * 2. To seal with Belzona 1161 ,
- * 3. Live leaks of hot well pump ,
- * 4. Stop leak with Belzona 1291 and Belzona 1161 ,

Application Situation

Drain pipe and hot well pump of a condenser

Application Method

The application was carried out in accordance with a modified of Belzona Know-How System Leaflet HEX-9 and CEP-6 . First, Belzona 1291 was used to stop the leak, then Belzona 1161 along with Belzona 9341 covered the area.

Belzona Facts

The traditional repair solution is not appropriate and loss a lot of time and cost, but Belzona solution is quick and easy, especially, can help the client reduce downtime and replacement cost.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA[®]
Repair • Protect • Improve