

# BELZONA SEALS GASOLINE STORAGE TANK

ID: 1499

Industry: *Chemical & Petrochemical*  
Application: *TCC-Tanks and Chemical Containment Areas*  
Substrate: *Steel*  
Products: *\* Belzona® 1161 (Super UW Metal) ,*

Customer Location: *Petrochemical plant, Ontario, Canada*  
Application Date: *Summer 2008*

## Problem

*Water was collecting on this large reinforcement seam causing extensive corrosion.*



## Photograph Descriptions

- \* Large corrosion area ,
- \* Severity of corrosion clearly evident ,
- \* Use of crane lift to access repair area ,
- \* Completed Application ,

## Application Situation

A large gasoline storage tank

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflet TCC-1. The application was completed from the support equipment (crane).

## Belzona Facts

Belzona® 1161 was used due to the difficulty in accessing and removing all condensation in the repair area. The application is in excellent condition until today without any problems.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve