

BELZONA PROTECTION ON RIVER BARRAGE

ID: 150

Industry: Marine

Application: CEP-Centrifugal Pumps

Substrate: Concrete

Products: * Belzona® 4911 (Magma TX Conditioner) Belzona® 1341 (Supermetalglide) ,

Customer Location: UK Commission for New Towns

Application Date: May 1999

Problem

The rubber seals on the moving gates were being damaged by the concrete walls when the barrage was raised and lowered.



Photograph Descriptions

- * The abrasion from the rubber seals clearly evident on the concrete ,
- * The completed application ,
- * The barrage in action ,

Application Situation

Flood defence barrage on tidal river

Application Method

Application carried out in accordance with Belzona Know-How system CEP-10.

Belzona Facts

Full scale application proceeded after initial trial proved 100% successful. Competitive system tried but could not be applied successfully. See KHIA Vol XXVI No 54 for update.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve