DUCT SEALING WITH BELZONA® 4211

ID: 153

Industry: General Industry Customer Location: Telecommunications in India

Application: VPF-Valves, Pipes and Fittings Application Date: August 1999

Substrate: Concrete, rubber and PVC

Products: *Belzona® 4211 (Magma-Stop) ,

Problem

Water leakage into the chambers causing cable joints to be submerged and extensive distruptions to telephone lines. Problem is particularly great during the monsoon.









Photograph Descriptions

- * Access to the chambers ,
- * The cable connections ,
- * & 4. Application of Belzona® 4211 underway,

Application Situation

Underground chambers containing cable joints

Application Method

Application was carried out in accordance with Belzona System Leaflet VPF-11b suitably modified.

Belzona Facts

"Live" leaks were effectively sealed eliminating major disruption to the local and national communication systems.

ISO 9001:2015

Belzona products are
FS 695214

ISO 14001:2015

Belzona products are
manufactured under an ISO
9000 Registered Quality
EMS 695213

Management System.

BELZONA®
Repair • Protect • Improve