

# BELZONA BELT SWAT TEAM

ID: 156

Industry: *Pulp & Paper*

Application: *SHM-Solids Handling Machinery*

Customer Location: *Paper Mill in Jacksonville, Florida*

Application Date: *September 1995*

Substrate: *Rubber*

Products: *\* Belzona® 2311 (SR Elastomer) ,  
\* Belzona® 2911 (Q.D. Conditioner) ,*

## Problem

*A small hole under belt tension is expected to get larger and debris was leaking through the belt.*



## Photograph Descriptions

- \* Belt delivers bark to powerhouse, 24 hours a day, 7 days a week ,
- \* Surface preparation completed using Belzona roughening brush, and Belzona® 2911 (Q.D. Conditioner) is applied ,
- \* Hole successfully patched by the happy crew (Belt Swat Team)! ,

## Application Situation

Conveyor belt

## Application Method

The application was carried out in accordance with Belzona Know-How Leaflet SHM-11.

## Belzona Facts

There was less than 1.5 hours from start to finish of the application. Little downtime resulted in significant cost savings to the paper mill.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

Copyright © Belzona International Limited 2024