

BELZONA FOOD PROCESSING FLOOR

ID: 157

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 4131 (Magma Screed) ,
* Belzona® 4111 (Magma Quartz) ,
* Belzona® 4151 (Magma Quartz Resins) ,

Customer Location: Food Processing Plant in Minnesota
Application Date: August 1995

Problem

The floor was badly deteriorated from constant wear and washings.



Photograph Descriptions

- * Severely damaged areas patched with Belzona® 4131 ,
- * Application of slurry Belzona® 4111/4151 system in progress ,
- * The completed application ,

Application Situation

Floor

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet FPA-1.

Belzona Facts

The customer has been using Belzona® 4000 series products for concrete repairs for the past seven years with excellent results. Despite the fact that a bid from another supplier was \$8000 less, the customer, based on past experience, elected to go with Belzona.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

