

BELZONA PROVIDES LONG TERM SOLUTION IN COOL ROOMS

ID: 1578

Industry: General Industry

Application: FPA-Floor Problem Areas

Substrate: Concrete

Products: * Belzona® 4131 (Magma Screed) ,
* Belzona® 2221 (MP Fluid Elastomer) ,
* Belzona® 5811 (Immersion Grade) ,

Customer Location: Poultry Plant, Virginia

Application Date: 1995

Problem

USDA inspectors made it clear that the leaks needed to be stopped. Floor needed to be repaired, coated and expansion joints sealed.



Photograph Descriptions

- * Second Floor Cooler ,
- * After Original Application ,
- * Floor After 14 Years ,
- * Only Small Damage Present ,

Application Situation

Second floor cooler (8500 ft²) was leaking onto the cooler on the lower floor.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & FPA-6.

Belzona Facts

After 14 years the floor was still water proof and without any leaks. Some scratches were present due to metal wheeled fork lifts but no water penetration. Small areas were touched up. Customer was very happy with longevity of the application.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve