

# EXTERNAL TANK CORROSION PROTECTION WITH BELZONA

ID: 1580

**Industry:** Chemical & Petrochemical

**Customer Location:** Fuel distribution company, Tamaulipas, Mexico

**Application:** TCC-Tanks and Chemical Containment Areas

**Application Date:** August 2000

**Substrate:** Carbon Steel

**Products:** \* Belzona® 6111 (Liquid Anode) Belzona® 5111 (Ceramic Cladding) ,

## Problem

Tank walls were suffering from external corrosion



## Photograph Descriptions

\* Surface preparation Applying Belzona® 6111 Application completed Tank ten years after application ,

## Application Situation

Oil storage tank

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

## Belzona Facts

10 years after the application, the inspection showed the Belzona product was in perfect condition. The Belzona application saved the customer an estimated US\$ 39,500 through reduced maintenance costs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA®**  
Repair • Protect • Improve