

EXTERNAL TANK CORROSION PROTECTION WITH BELZONA

ID: 1580

Industry: Chemical & Petrochemical

Customer Location: Fuel distribution company, Tamaulipas, Mexico

Application: TCC-Tanks and Chemical Containment Areas

Application Date: August 2000

Substrate: Carbon Steel

Products: * Belzona® 6111 (Liquid Anode) Belzona® 5111 (Ceramic Cladding),

Problem

Tank walls were suffering from external corrosion



Photograph Descriptions

* Surface preparation Applying Belzona® 6111 Application completed Tank ten years after application ,

Application Situation

Oil storage tank

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet TCC-5.

Belzona Facts

10 years after the application, the inspection showed the Belzona product was in perfect condition. The Belzona application saved the customer an estimated US\$ 39,500 through reduced maintenance costs.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA
Repair • Protect • Improve