

BELZONA UPGRADE TO FLOOR IN CHOCOLATE FACTORY

ID: 1588

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 5231 (SG Laminate) ,

Customer Location: Chocolate manufacturer, Derbyshire, UK
Application Date: December 2009

Problem

The existing coating had begun to deteriorate and sections of the main walk area had been removed exposing the concrete substrate beneath. This was not only unsightly; it also represented a health risk as staff were unable to clean the floor area adequately as food particles become trapped in the surface. The area also presented a considerable slip risk.



Photograph Descriptions

- * Floor Areas to be Repaired ,
- * Floor Areas to be Repaired ,
- * Completed Floor Application ,
- * Completed Floor Application ,

Application Situation

Floor in canteen wash area.

Application Method

The remainder of the original floor coating was uplifted and the whole concrete floor area Application was carried out in accordance with Belzona Know-How System Leaflet FPA-3.

Belzona Facts

The clients requirements and expectations have been met in full and they are very pleased with the results. the floor provides a hygienic surface that cannot harbour bacteria and also provides a slip resistant surface for the staff.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve