

# BELZONA UPGRADE TO FLOOR IN CHOCOLATE FACTORY

ID: 1588

Industry: General Industry  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona® 5231 (SG Laminate) ,

Customer Location: Chocolate manufacturer, Derbyshire, UK  
Application Date: December 2009

## Problem

The existing coating had begun to deteriorate and sections of the main walk area had been removed exposing the concrete substrate beneath. This was not only unsightly; it also represented a health risk as staff were unable to clean the floor area adequately as food particles become trapped in the surface. The area also presented a considerable slip risk.



## Photograph Descriptions

- \* Floor Areas to be Repaired ,
- \* Floor Areas to be Repaired ,
- \* Completed Floor Application ,
- \* Completed Floor Application ,

## Application Situation

Floor in canteen wash area.

## Application Method

The remainder of the original floor coating was uplifted and the whole concrete floor area Application was carried out in accordance with Belzona Know-How System Leaflet FPA-3.

## Belzona Facts

The clients requirements and expectations have been met in full and they are very pleased with the results. the floor provides a hygienic surface that cannot harbour bacteria and also provides a slip resistant surface for the staff.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**  
Repair • Protect • Improve