

# COLD PLATE BONDING WITH BELZONA RESTORES SUMP TANK

ID: 1590

Industry: Oil & Gas

Customer Location: Offshore Production Platform, Gulf of Mexico

Application: GSS-Gaskets, Seals and Shims

Application Date: October 2010

Substrate: Steel

Products: \* Belzona 1121 (Super XL Metal) ,

## Problem

Exposure to the elements and oil & gas process systems caused severe corrosion to exterior of sump tank bottom. Damage resulted in thin wall and through hole areas.



## Photograph Descriptions

\* 1. Corroded tank bottom 2.Sump bottom after blasting 3.New bottom jacked into place 4. Bonding completed ,

## Application Situation

Sump Tank Bottom deteriorated by external corrosion.

## Application Method

Applicaton was carried out in accordance with Belzona Know-How System Leaflet GSS-10. Belzona 1121 was used to cold bond pre-fabricated replacement bottom on the tank.

## Belzona Facts

Sump Tank had to be repaired or taken out of service. Welding was not suitable option because it would have required unit shut down and loss of production, and replacement would also have caused loss of production plus cost of new tank. Off site fabrication of a new tank bottom and temporary by pass of this tank during application was the most cost effective alternative.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA**<sup>®</sup>  
Repair • Protect • Improve