

# BELZONA UPGRADES FLOOR IN FOOD PREPARATION AREA

ID: 1596

Industry: Buildings & Structures  
Application: FPA-Floor Problem Areas  
Substrate: Concrete  
Products: \* Belzona® 5231 (SG Laminate) ,

Customer Location: School, UK  
Application Date: October 2010

## Problem

*The floor was slippery creating a health and safety issue. In addition the concrete was being damaged around drains.*



## Photograph Descriptions

- \* Floor Problem Area ,
- \* Floor Problem Area ,
- \* Completed Floor Application ,
- \* Completed Floor Application ,

## Application Situation

Floor in food preparation area.

## Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-3. The concrete was abraded to remove the existing coating before applying the 2 coat Belzona® 5231 system by roller.

## Belzona Facts

The school chose the Belzona solution for their floor problems as they wanted a seamless, hard-wearing and long lasting coating.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

They had a maximum of 4 days to complete the repair and Belzona were the only company able to accomodate this.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

|                |                           |
|----------------|---------------------------|
| ISO 9001:2015  | Belzona products are      |
| FS 695214      | manufactured under an ISO |
| ISO 14001:2015 | 9000 Registered Quality   |
| EMS 695213     | Management System.        |

[www.belzona.com](http://www.belzona.com)

