

BELZONA UPGRADES FLOOR IN FOOD PREPARATION AREA

ID: 1596

Industry: Buildings & Structures
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 5231 (SG Laminate) ,

Customer Location: School, UK
Application Date: October 2010

Problem

The floor was slippery creating a health and safety issue. In addition the concrete was being damaged around drains.



Photograph Descriptions

- * Floor Problem Area ,
- * Floor Problem Area ,
- * Completed Floor Application ,
- * Completed Floor Application ,

Application Situation

Floor in food preparation area.

Application Method

The application was carried out in accordance with Belzona Know-How System Leaflet FPA-3. The concrete was abraded to remove the existing coating before applying the 2 coat Belzona® 5231 system by roller.

Belzona Facts

The school chose the Belzona solution for their floor problems as they wanted a seamless, hard-wearing and long lasting coating.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

They had a maximum of 4 days to complete the repair and Belzona were the only company able to accomodate this.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015	Belzona products are
FS 695214	manufactured under an ISO
ISO 14001:2015	9000 Registered Quality
EMS 695213	Management System.

www.belzona.com

