

BELZONA SAVES AGRICULTURAL CHEMICAL COMPANY \$3 MILLION

ID: 160

Industry: Chemical & Petrochemical

Customer Location: A Large Multi-National Agricultural Chemical Company

Application: TCC-Tanks and Chemical Containment Areas

Application Date: October 1993

Substrate: Stainless steel vacuum piping, carbon steel drum

Products: * Belzona® 1221 (Super E Metal) Belzona® 2311 (SR Elastomer) ,

Problem

Leaks developed at the welds joining the vacuum lines to the face of the drum. The inside diameter of the drum was so deteriorated that there was some flexing at the drum face.



Photograph Descriptions

- * Belzona® 1221 around pipe, Belzona® 2311 on the drum around the Super E Metal patch ,
- * Beginning Belzona® 2311 patches ,
- * Completing Belzona® 2311 over Belzona® 1221 ,

Application Situation

10 ft. diameter x 12 ft. long filter drum used to manufacture Aureomycin

Application Method

The application was carried out in accordance with a modified version of Belzona Know-How Leaflet TCC-1.

Belzona Facts

After six weeks, the customer decided to check the repairs, believing that they were probably beginning to fail. Six repair areas were ground off, and no problems were observed. They were re-done as before, and the drum returned to service, saving the company over \$3 million.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

FS 695214

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 695213

Management System.

www.belzona.com

