

# BELZONA RESTORES HYGEINE IN BOTTLING ROOM

ID: 1605

Industry: Buildings & Structures

Customer Location: Bottled Water Manufacturer, Perthshire, UK

Application: FPA-Floor Problem Areas

Application Date: September 2010

Substrate: Concrete

Products: \* Belzona® 4131 (Magma Screed) ,  
\* Belzona® 5231 (S G Laminate) ,

## Problem

There were several cracked and broken tiles. This created a potential hygiene problem and required rectifying to remove traps for bacteria and to aid cleaning.



## Photograph Descriptions

- \* Damaged tiles being repaired with Belzona® 4131 ,
- \* Floor levelled with Belzona® 4131 ,
- \* Light grey Belzona® 5231 being applied ,
- \* Completed floor coating ,

## Application Situation

Tiled floor in bottling room.

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets FPA-1 & 3. Belzona® 4131 was used to replace loose tiles and create a uniform surface prior to application of the Belzona® 5231.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve

## Belzona Facts

The Belzona System creates a level, seamless surface that is hygienic in this critical area. The low VOC, low odour of the system was a further benefit in this bottling plant.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)



Copyright © Belzona International Limited 2024