

BELZONA SEALS TANK AT CABLE MANUFACTURER


ID: 1607

Industry: General Industry
Application: TCC-Tanks and Chemical Containment Areas
Substrate: Steel
Products: * Belzona® 1111 (Super Metal) ,
* Belzona® 5811 (Immersion Grade) ,

Customer Location: Cable manufacturer, US
Application Date: December 2010

Problem

Interior bottom cone of tank was leaking resulting in safety issues. severe corrosion pitting present particularly at the welded seams.



Photograph Descriptions

- * Exterior of tank ,
- * Pitted bottom after cleaning and blasting ,
- * Belzona® 1111 seals welds and holes ,
- * First coat of Beige® 5811 applied ,

Application Situation

Welded seam, oil storage tank.

Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets TCC-1 & 5. Welded seams and pits were sealed with Belzona® 1111. Two coats of Belzona® 5811 were applied.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve

Belzona Facts

Approximately \$2,000 of Belzona material was used on a \$32,000 tank extending the life and function of the tank. Belzona® 5811 provides long term corrosion protection in immersed conditions.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

