

BELZONA BUSHING REPAIR WITH BELZONA 1111

ID: 161

Industry: General Industry

Customer Location: A Large Construction Contractor in the State of Missouri

Application: MPT-Mechanical Power Transmission

Application Date: January 1994

Substrate: Carbon Steel

Products: * Belzona® 1111 (Super Metal) ,

Problem

The lift arm and bucket bushing fits were severely worn.



Photograph Descriptions

- * Cat 960 loader ,
- * Mandrel being inserted into the right hand bore to make the repair ,
- * Left side bucket pin installed and alignment pin removed ,

Application Situation

Caterpillar 960C Loader

Application Method

The application was carried out in accordance with Belzona Know-How Leaflet MPT-8.

Belzona Facts

Although the repair was done inside a shed, there was no heat and temperatures dropped below freezing. An oil fired heater was used to heat the repair areas around 80°F and left on all night to cure the Belzona® 1111 (Super Metal) completely.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com


BELZONA®
Repair • Protect • Improve