

# ROUTINE BELZONA TANK BASE SEALING APPLICATION

ID: 1616

Industry: Buildings & Structures

Application: CEP-Centrifugal Pumps

Substrate: Steel, concrete


Products: \* Belzona® 3111 (Flexible Membrane System) ,

Customer Location: Refinery, Thailand

Application Date: 2002- ongoing

## Problem

Bitumen sealant had failed to seal beneath the tank base allowing water penetration.



## Photograph Descriptions

- \* General view of the tank ,
- \* Deteriorated bitumen being removed ,
- \* Substrate conditioned ,
- \* Belzona® 3111 being applied to complete the system ,

## Application Situation

Fuel storage tanks

## Application Method

Application was carried out in accordance with Belzona® Know-How System Leaflets GSS-3.

## Belzona Facts

The flexibility of the Tank Base Sealing System is ideally suited to operation in this hot tropical climate. This is one of more than 50 such tanks now protected with the Belzona Tank Base Sealing System.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

FS 695214

ISO 14001:2015

EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

  
**BELZONA®**  
Repair • Protect • Improve