

BELZONA® 2211 SAVES EXPANSION JOINTS AT NEW AIRPORT

ID: 162

Industry: General Industry
Application: FPA-Floor Problem Areas
Substrate: Concrete
Products: * Belzona® 2211 (MP Hi-Build Elastomer) ,
* Belzona® 4111 (Magma Quartz) ,

Customer Location: New Metropolitan Airport
Application Date: October 1995

Problem

Outdoor expansion joints created hazards for people and equipment at the main loading and unloading gates.



Photograph Descriptions

* Backer rod with previous failed product pulled from joint, notice substrate chunks attached to failed product Close to the end of filling the joint. The cured section, ready for service ,

Application Situation

Outdoor expansion joints at main pasenger terminal

Application Method

The application was carried out in accordance with Belzona Know-How Leaflets FPA-5 and FPA-6.

Belzona Facts

Only Belzona® 2211 had the proper combination of hardness, elasticity, adhesive strength, and paste grade application control. A long shelf life allows the customer to purchase larger quantities with confidence and lets them continue repairs with products from stock as time permits.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015
FS 695214
ISO 14001:2015
EMS 695213

Belzona products are
manufactured under an ISO
9000 Registered Quality
Management System.

www.belzona.com

BELZONA
Repair • Protect • Improve