

# BELZONA® 2211 SAVES EXPANSION JOINTS AT NEW AIRPORT

ID: 162

**Industry:** General Industry  
**Application:** FPA-Floor Problem Areas  
**Substrate:** Concrete  
**Products:** \* Belzona® 2211 (MP Hi-Build Elastomer) ,  
\* Belzona® 4111 (Magma Quartz) ,

**Customer Location:** New Metropolitan Airport  
**Application Date:** October 1995

## Problem

Outdoor expansion joints created hazards for people and equipment at the main loading and unloading gates.



## Photograph Descriptions

\* Backer rod with previous failed product pulled from joint, notice substrate chunks attached to failed product Close to the end of filling the joint. The cured section, ready for service ,

## Application Situation

Outdoor expansion joints at main pasenger terminal

## Application Method

The application was carried out in accordance with Belzona Know-How Leaflets FPA-5 and FPA-6.

## Belzona Facts

Only Belzona® 2211 had the proper combination of hardness, elasticity, adhesive strength, and paste grade application control. A long shelf life allows the customer to purchase larger quantities with confidence and lets them continue repairs with products from stock as time permits.

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
FS 695214  
ISO 14001:2015  
EMS 695213

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

**BELZONA**  
Repair • Protect • Improve