

# BELZONA EXTENDS LIFE OF PULP BLENDER

ID: 1620

Industry: *Pulp & Paper*

Customer Location: *Paper mill, Spain*

Application: *ENC-Engines and Casings*

Application Date: *January 2007*

Substrate: *Steel*

Products: *\* Belzona® 1111 (Super Metal) ,  
\* Belzona® 1812 (Ceramic Carbide FP) ,*

## Problem

*Pump and bolt threads were severely damaged by the highly abrasive stream of shredded paper pulp flowing through it*



## Photograph Descriptions

- \* Pipe before application ,
- \* Applying Release Agent to the bolts ,
- \* Completed application ,
- \* View of the pipe after 3 &frac12; years service ,

## Application Situation

Outlet pipe of an industrial blender

## Application Method

Application was carried out in accordance with Belzona Know-How System Leaflets ENC-2 & SHM-11. The casing threads were reformed with Belzona® 1111 using the bolts treated with Belzona Release Agent as formers. The internals of the pipe were lined with Belzona® 1812.

## Belzona Facts

Prior to contacting Belzona, the company had to replace this piece of equipment every 1 or 2 years. An inspection of the Belzona

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015

Belzona products are

Q 09335

manufactured under an ISO

ISO 14001:2015

9000 Registered Quality

EMS 509612

Management System.

[www.belzona.com](http://www.belzona.com)

  
BELZONA®  
Repair • Protect • Improve

lining 3 ½ years later, in August 2010 showed it was still in place and none of the metal parts were exposed. As a result, the customer asked Belzona for several similar applications.

---

For more examples of Belzona Know - How In Action, please visit <https://khia.belzona.com>

ISO 9001:2015  
Q 09335  
ISO 14001:2015  
EMS 509612

Belzona products are  
manufactured under an ISO  
9000 Registered Quality  
Management System.

[www.belzona.com](http://www.belzona.com)

